

WÖHLER



CdYfUj]b['a Ubi U' 9B
J Ub'5]f': `ck 'A Yhf'

K "\ `Yf': 5 '(%\$'
K "\ `Yf': 5 '(' \$'

Contents

1	General Information.....	34
1.1	Operation Manual Information.....	34
1.2	Notes.....	34
1.3	Intended Use.....	34
1.4	Scope of supply for standard configuration .	34
1.5	Transport.....	34
1.6	Information on disposal	35
1.7	Adress	35
2	Fan anemometer specifications	36
3	Technical Data.....	36
4	Design and function	39
4.1	Fan anemometer components	39
4.2	Keypad	40
4.3	Display	41
5	Operating the fan anemometer.....	42
5.1	Powering on/off.	42
5.2	Selecting the measurement channel	43
5.3	Measuring volume flow.....	45
5.3.1	Measuring avec funnel	45
5.3.2	Measuring without measurement funnel.....	45
5.4	Determinating the air quality (only Wöhler FA 430)	47
5.4.1	Measuring relative humidity (Wöhler FA 430 only)	47
5.4.2	Measuring the CO ₂ concentration (Wöhler FA 430 only)	47
5.5	Freezing readings.....	47
5.6	Printing out data on the thermal printer	48
5.7	Displaying the lowest and highest measured values.....	49
5.8	Displaying the average value	50

5.8.1	Average value determined over time	50
5.8.2	Multi-point average	51
6	Settings.....	53
6.1	P1.0: Select unit.....	53
6.2	P2.0: Entering the area of the air outlet in cm ² or inch ²	54
6.3	P3.0: RH offset (Wöhler FA 430 only).....	54
6.4	P4.0: Entering the absolute pressure (Wöhler FA 430 only).	55
7	Calibration (Wöhler FA 430 only)	56
7.1	Calibrating the relative humidity.....	56
7.2	Calibrating the CO ₂ sensor	56
8	Replacing batteries	58
9	Faults	59
10	Error codes.....	59
10.1	Air temperature.....	59
10.2	Relative humidity	59
10.3	Dew point and wet-bulb temperature	60
10.4	Flow velocity	60
10.5	Volume flow	60
10.6	CO ₂	60
11	Service.....	61
11.2	Service.....	61
12	Declaration of Conformity	61
13	Accessories.....	62
14	Short guide.....	63

1 General Information

1.1 Operation Manual Information

This operation manual allows you to safely work with the Wöhler FA 410 / 430. Please keep this manual for your information.

The Wöhler FA 410 / FA 430 should be used by trained professionals for its intended use only.

Liability is void for any damages caused by not following this manual.

1.2 Notes



WARNING!

Not following this warning can cause injury or death.



ATTENTION!

Not following this note can cause permanent damage to the analyzer.



NOTE!

Useful information

1.3 Intended Use

Use the meter to measure the air velocity, temperature and humidity (only Wöhler FA 430) and the CO₂ concentration (only Wöhler FA 430) and to calculate the flow, dew point (only Wöhler FA 430) and wet-bulb temperature (only Wöhler FA 430). Together with a cone it is used to measure the air flow at vents.

1.4 Scope of supply for standard configuration

Fan anemometer	Components
Wöhler FA 410	Fan anemometer
or	4 x AAA batteries
Wöhler FA 430	Plastic case

1.5 Transport



CAUTION!

Improper transportation can lead to damage occurring to the fan anemometer!

To avoid damage occurring during transport it is imperative to transport the fan anemometer in the

original case designed for the purpose.

EN

1.6 Information on disposal



Electronic equipment does not belong into domestic waste, but must be disposed in accordance with the applicable statutory provisions.

You may hand in any defective batteries taken out of the unit to our company as well as to recycling places of public disposal systems or to selling points of new batteries or storage batteries.



1.7 Address

2 Fan anemometer specifications

This operating manual has been written for the Wöhler FA 410 and Wöhler FA 430 fan anemometers. That means it may contain descriptions that do not apply to the Wöhler FA 410. This is indicated in such instances. The differences between both fan anemometers are listed in the table below:

	Wöhler FA 410	Wöhler FA 430
Flow velocity	✓	✓
Volume flow	✓	✓
Temperature	✓	✓
Relative humidity		✓
Dew point		✓
Wet-bulb temperature		✓
CO ₂		✓

3 Technical Data

Range	Description	Wöhler FA 410	Wöhler FA 430
	Flow velocity	0.5 – 30 m/s	
	Volume flow (operating volume flow)	up to 99.999 m ³ /h	
	Temperature	-20.0 °C – 60 °C (-4 °F – 140 °F)	
	Relative humidity		0.1% – 99.9%
	Dew point		-20.0 °C – 59.9 °C (-4 °F – 139.82 °F)
	Wet-bulb temperature		-20.0 °C – 59.9 °C (-4 °F – 139.82 °F)
	CO ₂		0 – 9999 ppm

Resolution

Description	Wöhler FA 410	Wöhler FA 430
Flow velocity	0.1 m/s	
Volume flow	0.1 (0 – 9999.9) or 1 (10,000 – 99,999)	
Temperature	0.1 °C/F	
Relative humidity (RH)		0.1%
Dew point		0.1 °C/F
Wet-bulb temperature		0.1 °C/F
CO ₂		1 ppm

Accuracy

Description	Wöhler FA 410	Wöhler FA 430
Flow velocity	±(1,5% of reading + 0,3 m/s) for under 20m/s	
	±(3% of reading + 0,3 m/s) for above 20 m/s	
Volume flow	0.2% of measurement reading	
Temperature	0.6 °C / 33.08 °F	
Relative humidity		±3% (at 25 °C / 77 °F) otherwise ±5%
CO ₂		± 30 ppm ±5% of reading (0 – 5000 ppm)

Technical Data

Miscellaneous

Description	Wöhler FA 410	Wöhler FA 430
CO ₂ warm-up time		30 seconds
Operating conditions (to avoid condensation)	0 – 50 °C (32 – 122 °F), < 80% RH	
Storage conditions	-10 – 50 °C (14 – 122 °F), < 90% RH	
Power supply	4 micro batteries AAA	
Battery life	> 40 hours	> 24 hours
Fan anemometer dimensions	269 x 106 x 51 mm	
Fan diameter	Ø 10 cm	
Weight (without funnel)	270 g	

4 Design and function

4.1 Fan anemometer components




Fig. 1: Fan anemometer components

Front view

- 6 Handle
- 7 Keypad
- 8 IR interface
- 9 Display
- 10 Fan

Rear view

Battery compartment

4.2 Keypad



Fig. 2: Keypad

The fan anemometer is operated using four keys. The keys have the following functions



ON/OFF key

- Press briefly: Power on/off
- Press and hold: Access and exit Setup mode



HOLD/MIN/MAX key

- Press briefly: Freeze current reading; continue to press the key after freezing to begin printing.
- Press and hold: Display the lowest and highest measured value (MIN, Max)
- In the Average value mode (AVG): Save data or begin calculating averages over a specified time.
- In the Setup mode: Make settings




Up key

- Toggle between readings displayed in the top part of the display (Wöhler FA 430 only)
- Press and hold: Access the Average value mode (AVG)
- In the Average value mode (AVG): Display average value and return to normal Measuring mode
- In the Setup mode: Select a parameter and increase a value



Down key

- Toggle between readings displayed in the lower part of the display
- In the Average value mode (AVG): Display the average values of all measured quantities
- In the Setup mode: Select a parameter and lower a value



Deactivate Auto-Off function.



Access Calibration mode

4.3 Display

After the fan anemometer is powered on, the whole of the display is briefly filled with all possible values.



Fig. 3: Fully display

The display is structured as follows:



Top part of display

Displays flow velocity, relative humidity, CO₂ value (Wöhler FA 430 only), measurement duration in Average value mode.

Lower part of display

Displays temperature, volume flow, wet-bulb temperature and dew point

The abbreviations and symbols have the following meaning:

HOLD	Freeze the current display
MAX MIN	Highest and lowest values
AVG	Averaging
	Low battery warning
m/s; fpm	Flow velocity display units
ppm	CO ₂ display unit
RH	Relative humidity
°C and °F	Temperature display units
m ³ /h, CFM	Volume flow display units
WBT	Wet-bulb temperature
DP	Dew point temperature
Inch ² ; cm ²	Area display units
	Funnel symbol

5 Operating the fan anemometer

5.1 Powering on/off.




Fig. 4: Fully display

- To power on the fan anemometer, briefly press the On/Off key.

All possible symbols and units are displayed for about 1 second.

The Wöhler FA 410 switches immediately to the normal Measuring mode.

The Wöhler FA 430 switches to the normal Measuring mode after a warm-up time of approx. 30 seconds.

- To power off the fan anemometer in any mode, briefly press the On/Off key.

Auto-Off function

The fan anemometer automatically powers off if no keys are operated for 20 minutes.




Fig. 21: Deactivate the Auto-Off function

To deactivate the Auto-Off function, proceed as follows:

- With the fan anemometer powered off, press and hold the On/Off and AVG keys simultaneously for 2 seconds.

"n" is shown on the display before the fan anemometer switches to the normal Measuring mode (Wöhler FA 410) or the warm-up phase begins (Wöhler FA 430).

The Auto-Off function is deactivated, the fan anemometer will now not power off automatically.

To re-activate the Auto-Off function power the fan anemometer off and on again.

5.2 Selecting the measurement channel



Fig. 5: Flow velocity and air temperature display

After the fan anemometer is powered on, the flow velocity is displayed in the top part of the display and the air temperature is displayed in the lower part of the display.



Wöhler FA 430

- To toggle between displayed readings in the top part of the display, briefly press the Up key.

The flow velocity, relative humidity and the CO₂ readings are displayed in succession.

Wöhler FA 410

It is not possible to toggle between readings in the top part of the display.



Wöhler FA 430

- To toggle between displayed readings in the lower part of the display, briefly press the Down key.

The air temperature, volume flow, wet-bulb temperature and dew point readings are displayed in succession.

Wöhler FA 410

- To toggle between displayed readings in the lower part of the display, briefly press the Down key.

The air temperature and volume flow are displayed in succession.

5.3 Measuring volume flow

5.3.1 Measuring avec funnel

Important Notes:

- When measuring the volume flow of a ceiling diffuser or of an axial valve, use the Wöhler funnel with the twist adjusting device (artikel 4164 or 23501), see accessories.

Before measuring the outlets of a push-pull-device, check if it works with an axial valve. In this case use the twist adjusting device.

It is recommended to use a measurement funnel when taking measurements at air passages.

A 346 x 346 mm square funnel and a Ø 210 mm round funnel are available to attach to the fan anemometer, please refer to the Chapter Accessories.

- Insert the fan anemometer into the funnel clamp.
- To secure, slide the lever next to the fan anemometer upwards (indicated by an arrow in the image opposite).

When the fan anemometer is securely seated in the clamp it automatically recognizes that a funnel has been attached. The funnel symbol is shown in the display.



Fig. 6: Wöhler FA 410/430 with round funnel attached



NOTE!

The readings now automatically take the installed funnel into consideration for the calculation of the volume flow.



CAUTION!

When taking measurements, make sure the fan anemometer is securely seated in the clamp of the funnel. Only then is the funnel symbol shown in the display. Measurements undertaken using the funnel when the funnel symbol is not shown in the display do not return correct results.



Fig. 7: Funnel symbol

5.3.2 Measuring without

- Before beginning air flow measurements, enter the area of the air outlet in the Setup

measurement funnel

mode, please refer to the Chapter 6.2.



NOTE!

For the measurement of the volume flow at air passages without funnel we recommend the measurement mode "Average value determined over time".(chapter 5.8.1)

- When starting the measurement mode , direct the fan anemometer slowly and steady over the entire area of the air passage.



HINWEIS!

Make sure to stop the measurement by pressing the button immediately after the data record has been finished, because the calculation of the average will not be correct, if the average measurement mode is stopped after the device has been removed from the air passage.

5.4 Determinating the air quality (only Wöhler FA 430)

A good air quality is decisive for the comfort of persons. Therefore many new guidelines, e.g. VDI 6022-3 and DIN EN 15251, are based on the determination of the air quality. The Wöhler FA 430 does not only determine the amount of circulating air but it also determines the quality of this air. According to VDI 6022-3 and DIN EN 15251 the humidity and the CO₂ are the most important parameters. The Wöhler FA 430 measures these values and the volume flow at the same time.

5.4.1 Measuring relative humidity (Wöhler FA 430 only)

- Press the Up key until the relative humidity is displayed in the top part of the display.



NOTE!

It is possible to set an offset value for the relative humidity in the Setup menu, please refer to Chapter 6.3.

5.4.2 Measuring the CO₂ concentration (Wöhler FA 430 only)

- Press the Up key until the CO₂ reading is displayed.



NOTE!

When measuring at high altitudes, take the pressure into consideration to obtain a precise CO₂ reading. Before beginning to take measurements at high altitudes, enter the absolute pressure of your location under position 4.0 in the Setup mode; please refer to Chapter 6.4.

5.5 Freezing readings



- Press the HOLD/MIN/MAX key.

The readings in the top and lower parts of the display are frozen.

- To return to the normal Measuring mode, press the HOLD key again.

5.6 Printing out data on the thermal printer



You can print out readings by transmitting them to a thermal printer via the infrared interface.

- In the normal Measuring mode, briefly press the HOLD/MIN/MAX key to freeze the current reading.
- In the Hold mode, press and hold the HOLD/MIN/MAX key for 2 seconds to begin transmitting the data to the thermal printer.



NOTE!

Make sure the infrared interfaces of the fan anemometer and the thermal printer are directly facing one another.

Data transmission and printout on the thermal printer will begin. "Print" flashes in the display of the fan anemometer as long as data is being transmitted.

The values of all measurement channels are printed out, not just those readings visible on the display. Furthermore, the area of the air outlet entered in the Setup menu will be printed, if there is no funnel installed while printing. If the funnel is installed while printing, the area cross section of the funnel, on which the volume flow calculation has been based, will appear on the printout.



Note!

After measuring with a funnel, printing should be done while the funnel is still mounted.

The Date, Signature and Remarks fields are also printed out for the operator to complete.

5.7 Displaying the lowest and highest measured values



Fig. 8: Maximum value

- When in the normal Measuring mode, press and hold the HOLD/MIN/MAX key for 3 seconds.

The lowest measured values are displayed. MIN is shown in the display.

- Press and hold the HOLD/MIN/MAX key again for 3 seconds.

The highest measured values are displayed. MAX is shown in the display.

- To return to the normal Measuring mode, press and hold the HOLD/MIN/MAX key again for 3 seconds.
- To toggle between the individual readings on the display when in the MIN or MAX mode, press the Up key (top part of the display) or the Down key (lower part of the display).

5.8 Displaying the average value

The fan anemometer calculates the time-averaged and multi-point average of all measured quantities.

5.8.1 Average value determined over time




Fig. 9: Time-averaged value display



Fig. 10: Average value determined over time

- In the normal Measuring mode, press and hold the Up key for 2 seconds to access the **Multi-point average mode**.
- Press the key again briefly to access the **Time-averaged reading mode**.

A clock and AVG are shown in the display.

- Press the HOLD/MIN/MAX key to start the measurement.
- Direct the fan anemometer slowly and steady over the entire area of the air passage.
- Press the Up key to end measurements.



NOTE!

Make sure to stop the measurement by pressing the button immediately after the data record has been finished, because the calculation of the average will not be correct, if the average measurement mode is stopped after the device has been removed from the air passage.

The duration of the measurement is displayed in the top part of the display; the average value is displayed in the lower part of the display. AVG flashes.

- Press the Down key to toggle between the average values of the different measured quantities.





- To obtain a printout, press and hold the HOLD/MIN/MAX key.

"Print" is shown in the display.

! CAUTION!

After returning to the normal measuring mode, the average values will no longer be shown. Therefore we recommend to print them out for documentation.



5.8.2 Multi-point average



Fig. 11: Average value mode, multi-point



- To return to the normal Measuring mode, press the Up key.
- In the normal Measuring mode, press and hold the Up key for 2 seconds to access the Multi-point average mode.

A dot and AVG are displayed in the top part of the display.

The number of stored measurement readings is displayed in the top part of the display; the current reading is displayed in the lower part of the display.



Fig. 12: Average value display, multi-point



- To save a measurement reading, press the HOLD/MIN/MAX key.
- Repeat this process at various points.
- When a sufficient number of measurement readings have been saved, press the Up key to display the average value. AVG flashes.
- Press the Down key to toggle between the average values of the different measured quantities.



- To obtain a printout, press and hold the HOLD/MIN/MAX key.

"Print" is shown in the display.



CAUTION!

After returning to the normal measuring mode, the average values will no longer be shown. Therefore we recommend to print them out for documentation.



- To return to the normal Measuring mode, press the Up key.

6 Settings

In the Setup mode, the user is able to configure settings to achieve measurement results of the utmost accuracy. The following settings are possible:

P1.0: Select unit

P2.0: Entering the area of the air outlet

P3.0: RH offset

P4.0: Enter the air pressure (Wöhler FA 430 only).



Fig. 13: Setting mode



6.1 P1.0: Select unit




Fig. 14: Setting mode – selecting the unit of measurement

- In the normal Measuring mode, press and hold the On/Off key for 2 seconds to access the Setup mode.

The P1.0 mode is displayed.

- Press the Up or Down key to access the modes P1.0 to P4.0.
- To do settings, go immediately to chapter 6.1.

- To return to the normal Measuring mode, press and hold the On/Off key again for 2 seconds.

- In the P1.0 mode, press the HOLD/MIN/MAX key to access the Unit of measurement mode.
- Using the Up and Down keys, toggle between the screen displaying metric (European) units of measurement (m/s, °C, m³/h, cm²) and the screen displaying the imperial (US) units of measurement (fpm; °F, CFM and inch²).

It is possible to choose between the following units:

Flow velocity: m/s and fpm

Temperature: °C and °F

Volume flow: m³/h and CFM

Area: cm² and inch²



- To return to the P1.0 mode, press the HOLD/MIN/MAX key.

6.2 P2.0: Entering the area of the air outlet in cm² or inch²




Fig. 15: Entering the area

- In the P2.0 mode, press the HOLD/MIN/MAX key to access the Area entry mode.

A five-digit figure is displayed. The first digit flashes.

- Set the first digit using the Up key.



- Move to the next digit using the Down key. Set this digit as described above.

- When you have finished setting the figure, press the HOLD/MIN/MAX key to save the entry and return to the P2.0 mode.

6.3 P3.0: RH offset (Wöhler FA 430 only)

If an offset value is entered, the fan anemometer fundamentally adds the entered offset value to the measured value.



Fig. 16: Setting the offset value

- In the P3.0 mode, press the HOLD/MIN/MAX key to access the Offset setting mode.

The offset value will now flash in the display

- Using the Up and Down keys, set an offset value between 0 and 12% RH.



- Move to the next digit using the Down key. Set this digit as described above.

- To return to the P3.0 mode after completing the setting, press the HOLD/MIN/MAX key.

6.4 P4.0: Entering the absolute pressure (Wöhler FA 430 only).

When measuring at high altitudes, take the pressure into consideration to obtain a precise CO₂ reading. Before beginning to take measurements at high altitudes, enter the absolute pressure of your location .



- In the P4.0 mode, press the HOLD/MIN/MAX key to access the Absolute pressure setting mode.

The preset absolute pressure is displayed in hectopascal (1013 hPa).



Fig. 17: Entering the absolute pressure

- Using the Up and Down keys, set the absolute pressure of the location where you are taking measurements.



- To return to the P4.0 mode after completing the setting, press the HOLD/MIN/MAX key.

7 Calibration (Wöhler FA 430 only)

- 7.1 **Calibrating the relative humidity** The user is not authorized to calibrate the relative humidity. If it becomes necessary to calibrate the relative humidity, return the fan anemometer to the factory or send it to an approved service center.
- 7.2 **Calibrating the CO₂ sensor** The fan anemometer is calibrated ex-works to a CO₂ concentration of 400 ppm. However, it should be manually calibrated regularly outside in the fresh air to guarantee accurate measurements.
- Return the fan anemometer to the factory if it has been used for a long time without being calibrated.



CAUTION!

Never calibrate the fan anemometer when the CO₂ concentration is unknown. Otherwise, the fan anemometer sets the calibrated value equal to 400 ppm which in turn will lead to incorrect measurement results.

Carry out manual calibration on a sunny day outside in the fresh air, for example on the outside windowsill, when the CO₂ concentration is approx. 400 ppm.

**NOTE!**

A rainy day is not suitable due to the high air humidity, and because it can affect the CO₂ concentration in the air.

Locations with high levels of CO₂ concentration are not suitable places to calibrate the fan anemometer, e.g. locations where a lot of people congregate or near exhaust air openings or fireplaces.

**CAUTION!**

Before calibrating the fan anemometer, make sure the battery warning symbol is not shown on the display. Empty batteries can lead to the calibration process being aborted.

- Power off the fan anemometer.
- To access the CO₂ calibration mode, simultaneously press and hold the On/Off key, the HOLD/MIN/MAX key and the Down key for 2 seconds.

CAL is shown in the display and the fan anemometer counts down 30 seconds. Then the calibration process begins.

During the calibration process a value ranging between 380 and 420 ppm flashes in the top part of the display.

The value stops flashing after approx. 10 minutes. The 400 ppm calibration is finished and the fan anemometer returns to the normal Measuring mode.



Fig. 18: Calibrating the CO₂ sensor

**NOTE!**

To interrupt the calibration process at any time, simply power off the fan anemometer.

- 8 Replacing batteries** The battery symbol is shown in the display when the battery voltage is low.
- In the event the battery symbol is displayed, replace the batteries as follows:
 - Open the battery compartment on the rear of the fan anemometer by simultaneously pressing down on the small tab above the lid and sliding off the lid at the same time.
 - Replace the batteries with four new AAA batteries. Insert the batteries according to the polarity markings inside the compartment.

9 Faults

EN

Fault	Possible cause	Remedy
It is not possible to power on the fan anemometer	On/Off key pressed too fleetingly	Press the On/Off key slightly longer
	Batteries not inserted correctly	Check correct polarity
	Battery voltage insufficient	Replace batteries

10 Error codes

10.1 Air temperature

Error code	Error	Remedial action
E02	Temperature is below measuring range	Acclimatize the fan anemometer at room temperature for 30 minutes. If E02 is still displayed, return the fan anemometer for repair.
E03	Temperature is above measuring range	Acclimatize the fan anemometer at room temperature for 30 minutes. If E02 is still displayed, return the fan anemometer for repair.
E31	Temperature sensor defective	Return the fan anemometer for repair.

10.2 Relative humidity

Error code	Error	Remedial action
E04	Caused by temperature error	Please refer to paragraph 10.1
E11	Calibration error	Return the fan anemometer for relative humidity calibration
E31	Moisture sensor defective	Return the fan anemometer for repair.

10.3 Dew point and wet-bulb temperature

Error code	Error	Remedial action
E04	Caused by temperature or humidity error	Please refer to paragraphs 10.1 and 10.2.

10.4 Flow velocity

Error code	Error	Remedial action
E03	Flow velocity is above range	Take measurements within range. If E03 is still displayed, return the fan anemometer for repair.

10.5 Volume flow

Error code	Error	Remedial action
E03	Value is above display range.	Check entered tube area.
E04	Error with flow velocity	Return the fan anemometer for repair.

10.6 CO₂

Error code	Error	Remedial action
E03	Temperature is above measuring range	Acclimatize the fan anemometer at room temperature for 10 minutes. If E03 is still displayed, return the fan anemometer for repair.
E01/E33	Low battery voltage or CO ₂ sensor error	If the battery symbol is displayed, replace batteries. Manually calibrate the CO ₂ sensor

11 Service

EN

Test Equipment Depot - 800.517.8431 - 99 Washington Street Melrose, MA 02176
TestEquipmentDepot.com

12 Declaration of Conformity

The product:

Name: Van Air Flow Meter

Modell: Wöhler FA 410 and FA 430

has been tested in accordance to essential protection requirements of Council Directive 2014/30/EU and found the test results indeed meet the limitation of the relevant test standards.

13 Accessories

Printer

Wöhler TD 100 Thermoprinter Art. n° 4160

Measurement funnel

Wöhler FA 4xx Measurement funnel kit with a rectangular and a circular measurement funnel that can be plugged on the fan anemometer Art. n° 4148

Rectangular funnel 346 x 346 mm

Circular funnel Ø 210 mm

Twist adjusting device

Funnel with twist adjusting device Art. n° 4164

Twist adjusting device Art. n° 23501

Telescope bar

Telescope bar for the measurement funnel Wöhler FA 4xx Best.-Nr. 4684

14 Short guide

EN

