S	ULTRA™ THERMOMETER ACCURACY	DATA HOLD	BATTERY REPLACEMENT
–58 to 572 °F –50 to 300 °C	Ultra [™] thermometers are tested at selected test points to be within tighter than normal tolerances to assist in providing improved accuracy. Other points	Slide the HOLD/TEST switch to TEST to make measurements. Slide the HOLD/TEST switch to HOLD to "freeze" the display at the current reading "FIFC"	Erratic readings, a faint display indications that the battery mu replace the battery, remove the
Cat. No. 4050 ±1.5°C	will not necessarily fall within the same accuracy as those found at the selected test points, but will be	will flash on the display. Once the reading has been recorded, slide the HOLD/TEST switch to TEST to	it in the direction indicated by the Remove the exhausted battery
Cat. No. 4350	within an accuracy of ± 1.5 °C.	"release" the display and return to the current read-	a new 1.5 volt size G-13 batter
±0.4°C at tested points	OPERATION	ing, °F/°C will no longer flash on the display.	No. 1039). Make certain that to facing you. Replace the batter
±1.5°C otherwise	 Remove the stem from the protective sheath. 	ALL OPERATIONAL DIFFICULTIES	lacing you. Replace the batter
0.1° from –20 to 200	Slide the ON/OFF switch to ON.	If this thermometer does not function properly for any	
(otherwise 1°)	·	, , , , , , , , , , , , , , , , , , , ,	
1 second	perature in Fahrenheit or to °C to display the temperature in Celsius.	quality battery (see "Battery Replacement" section). Low battery power can occasionally cause any num-	
31/2" (8.9 cm)	4. Slide the HOLD/TEST switch to TEST and insert	ber of "apparent" operational difficulties. Replacing	
0.15" (3.8 mm)	the stem of the thermometer into the material to be measured.	the battery with a new fresh battery will solve most difficulties. If the voltage of the battery becomes low	
7" (17.8 cm)	Slide the ON/OFF switch to OFF.	°C and °F symbols will flash.	
	-50 to 300 °C Cat. No. 4050 ±1.5°C Cat. No. 4350 ±0.4°C at tested points ±1.5°C otherwise 0.1° from -20 to 200 (otherwise 1°) 1 second	Ultra™ thermometers are tested at selected test points to be within tighter than normal tolerances to assist in providing improved accuracy. Other points to be within tighter than normal tolerances to assist in providing improved accuracy. Other points will not necessarily fall within the same accuracy as those found at the selected test points, but will be within an accuracy of ±1.5°C. Cat. No. 4350 ±0.4°C at tested points ±1.5°C otherwise 0.1° from −20 to 200 (otherwise 1°) 1. Remove the stem from the protective sheath. 2. Slide the ON/OFF switch to ON. 3. Slide the °F/°C switch to °F to display the temperature in Celsius. 3½" (8.9 cm) 4. Slide the HOLD/TEST switch to TEST and insert the stem of the thermometer into the material to be measured.	Ultra™ thermometers are tested at selected test points to be within tighter than normal tolerances to assist in providing improved accuracy. Other points to "freeze" the display at the current reading, "F,"C will not necessarily fall within the same accuracy as those found at the selected test points, but will be those found at the selected test points, but will be within an accuracy of ±1.5°C. Cat. No. 4350 ±0.4°C at tested points ±1.5°C otherwise OPERATION 1. Remove the stem from the protective sheath. 0.1° from −20 to 200 (otherwise 1°) 1. second 2. Slide the ON/OFF switch to ON. 3. Slide the °F/°C switch to °F to display the temperature in Fahrenheit or to °C to display the temperature in Celsius. 3½" (8.9 cm) 4. Slide the HOLD/TEST switch to TEST to make measured. Slide the HOLD/TEST switch to TEST to to "freeze" the display at the current reading, °F/°C will fash on the display. Once the reading has been recorded, slide the HOLD/TEST switch to TEST to "release" the display and return to the current reading, °F/°C will no longer flash on the display. ### The display at the current reading, °F/°C will no longer flash on the display. ### The display at the current reading, °F/°C will no longer flash on the display at recorded, slide the HOLD/TEST switch to TEST to "release" the display at the current reading, °F/°C will no longer flash on the display. ### The display at the current reading, °F/°C will no longer flash on the display at the current reading, °F/°C will no longer flash on the display at the current reading, °F/°C will no longer flash on the display at the current reading, °F/°C will no longer flash on the display. #### The display at the current reading, °F/°C will no longer flash on the display. #### The display at the current reading, °F/°C will no longer flash on the display. ### The display at the current reading, °F/°C will no longer flash on the display at the current reading, °F/°C will no longer flash on the display at the current reading, °F/°C will no longer fl

6. Replace the protective sheath.

Battery:

Cat. No. 1039

readings, a faint display, or no display are all tions that the battery must be replaced. To

e the battery, remove the battery cap by turning e direction indicated by the "OPEN" arrow. ve the exhausted battery and replace it with

1.5 volt size G-13 battery (Replacement Cat. 39). Make certain that the positive (+) side is you. Replace the battery cap.

WARRANTY, SERVICE, OR RECALIBRATION For warranty, service, or recalibration, contact:

CONTROL COMPANY

Control Company is ISO 9001:2008 Quality-Certi ied by DNV and ISO/IEC 17025:2005 accredited as a Calibration Laboratory by A2LA.



Test Equipment 5 Commonwealth Ave Woburn, MA 01801

TestEquipmentDepot.com

(c) Control Company Cat. No. 4050/4350 Traceable® is a registered trademark of Control Company. ©2016 () Control Company. 92-4050-10 Rev. 6 061316

TRACEABLE® POCKET THERMOMETER INSTRUCTIONS