

Instruction Sheet

Cyclops 2 Cable Jacket Stripper

P/N 15010




Application

CYCLOPS 2

Stripping tool for removing cable jackets from twisted pair cable (UTP/STP), single & multi-core cables and fiber optic cable.


Accepts cable diameters to .43" (11 mm) diameter.

Self adjusting.




1. Opening the tool

Pull on the ring with the middle finger and push on the side grips with the thumb and forefinger.




2. Inserting the Cable

Open the tool and insert the length of cable to be stripped.




3. Operation



4. Removing the insulation

Open and remove the tool from the cable.

Bend and pull off the outer insulation.



PLATINUM TOOLS

IS_15010 Rev B.pub
©Platinum Tools, Inc. 2005

Test Equipment Depot
1-800-517-8431

99 Washington Street
Melrose, MA 02176
Phone 781-665-1400
Toll Free 1-800-517-8431

Visit us at www.TestEquipmentDepot.com