

COMPONENTS FOR CONNECTING



The Kevlar[®], which is used in the coating of optical fiber, is a high hardness and shear strength material. Therefore, when cutting Kevlar [®] is essential a cutting tool with high durability blades. The scissors provided by **PROMAX** make a clean cut, and they are also very comfortable to use thanks to its plastic cover.

The Kevlar[®] scissors are available as a separate accessory, being part of the **PL-10 Connecting Kit** or part of the **OP-040 Fusion Extension Kit**, which in a suitcase includes all the most important tools and accessories to make inexpensive fiber connections.



