

Phase Sequence Indicator

K-7-1



The K-7-1 Phase Sequence Indicator indicates the order of succession in time of the different voltage peaks of a multi-phase supply. The K-7-1 is used to make three-phase circuit installations or alterations as well as replacement installations of motors and generators. It can be used for making continuity tests of circuits of poly-phase systems. It is also valuable in making connections of power-factor meters, voltampere meters, watt and watt-hour meters and relays.

- Indicates the phase sequence by the direction of the rotor disc
- Voltage range from 60 – 600V
- Protects valuable equipment against damage
- No range switching or lamps
- 3 - 36" long connected leads with red, white and blue clip insulators
- Lightweight and easy to carry – 21 ounces



1-800-517-8431

99 Washington Street
Melrose, MA 02176
Phone 781-665-1400
Toll Free 1-800-517-8431

All sales are subject to the terms and conditions of the Limited Warranty and Limitation of Liability set forth in the product Instruction Manual and at www.HDElectricCompany.com. Users must read and agree to the Limitation terms, as stated, before using the product. HD Electric Company is committed to ongoing review and improvement of its product lines, and thus reserves the right to modify product design and specifications without notice. HD Electric Company® products are available through HDE® sales representatives worldwide. Printed in U.S.A. © HD Electric Company 2019 • Bulletin No. K-7-1-200a

Visit us at www.TestEquipmentDepot.com