

## **QTFT-CAPB**

Cap, plug, chain and hanger ring, brass (for any brass Quicktest adapter)

Cap any male Quick-test adapter with a cap and chain

## **Features**

• Seals any male Quick-test adapter to 5000 psi



## **Specifications**

| Pressure Range                 | 0 to 5000 psi (0 to 345 bar)               |
|--------------------------------|--|
| End C1                         | Female Quick-test with cap, chain and plug |
| Has Check Valve                | No   |
| Maximum Working<br>Temperature | 140 °F (60 °C)                             |
| Dimensions A                   | 0.85 in (2.16 cm)                          |
| Dimensions B                   | 0.7 in (1.78 cm)                           |

Test Equipment Depot 1-800-517-8431

99 Washington Street Melrose, MA 02176 Phone 781-665-1400 Toll Free 1-800-517-8431

Visit us at www.TestEquipmentDepot.com