



## HOBO<sup>®</sup> S-FS-TRMSA Sensor

### FlexSmart TRMS Module (2 channels) Sensor


The 15-bit two-channel FlexSmart True RMS Current / Voltage Module accepts an input range of 5mV to 512mV and is compatible with 333mV FS output sensors. Field wiring is 2-wire via screw terminals.



#### Key Advantages:

- 2 input channels of AC Current and/or Voltage
- Measures True RMS for accurate readings of sinusoidal and non-sinusoidal waveforms

## HOBO S-FS-TRMSA Sensor Specifications

Input Channels	Two; AC-coupled
Field Wiring	Two-wire via screw terminals on detachable connector, 16-24 AWG Replacement detachable connectors: Part of spares kit (A-FS-TRMSA-4P-1)
Input Range	5 to 512 mVRMS
Minimum Input Voltage	5mVRMS; Input voltages < 5mV will be clipped to zero (see graph below)
Maximum Input Voltage	±1V referred to AC- terminals (pins 2 and 4)
Input Frequency	50/60 Hz
Accuracy	±0.3% of reading +/- 0.5% of FSR
ADC Resolution	15 bits
AC Waveform	<4 Crest Factor
Power Requirements	+3.3V @ 3mA active, 6A sleep
Transfer Function	
Measurement Averaging Option	Yes
	The CE Marking identifies this product as complying with all relevant directives in the European Union (EU).